

1" to 2" variation



Shoving /wash-boarding
poor paving techniques



1.5" to 2"

1.5" depression approaching MH
potential icing hazard and
ponding issues



Tears in Mat

1.5"

1.25"

